



Photo 1. Beaver dam located in east-central portion of property, facing west.



Photo 2. Beaver-created pond, facing north. Note dam on center-right.



Photo 3. Sandy Creek showing typical width and bank substrate.



Photo 4. View from upper elevations of central portion of property.